



WINDOW SEALANT GLAZING INSPECTION

PERTH, WA

SPECIALIST ACCESS - INSPECTION

PROJECT

80 Stirling Street Window Sealant Glazing Inspection

CLIENT

Knight Frank

DURATEC CONTACT

Jonas De Prose 0421 395 171

DESCRIPTION

Duratec was engaged to inspect all facades of the building by rope access as no other access method could be used due to the building's location.

Defects were quantified, recorded and referenced by photograph for ease of remedial workscope.

The resulting inspection report was utilised by the client as a tender specification for repair, including bills of quantities.

HIGHLIGHTS

- ▶ Inspection completed within scheduled completion time and budget.



IMAGES (FROM TOP TO BOTTOM)

- ▶ Overview of the building in Northbridge.
- ▶ Degraded condition of window seals.
- ▶ Rope access inspection to external facades.